



DIRECCIÓN GENERAL DE
AVIACIÓN CIVIL
COSTA RICA

TEL/FAX: (506)2220-0923
AFS: MROCYOYX
Web page: www.dgac.go.cr
e-mail: aiscr@dgac.go.cr

REPUBLIC OF COSTA RICA
CIVIL AVIATION DIRECTION GENERAL
Air Navigation Department
AIS/MAP
P.O. BOX 5026 -1000
SAN JOSE – COSTA RICA

AIP

Supplement A08/10
May 03, 2010

TOBIAS BOLAÑOS INTERNATIONAL AIRPORT **AERODROME CHART**

Starting from May 04 2010 and permanent it is published the up dated, “Aerodrome Chart” of Tobías Bolaños International Airport, (MRPV AD1) including new taxiways and changes on nomenclature. The rapid exit taxiway denominated: **A3** is strictly used by aircrafts Cat **A** and **B**.

CHART IS ATTACHED
NOTAM A203/10, A0208/10 ARE CANCELED
CHART MRPV AD1 IS REPLACED WITH MODIFICATIONS

Visit our web page: www.dgac.go.cr and update your information.

AERODROME CHART

N 09° 57' 25.70441"
W 84° 08' 22.41736"


TOBIAS BOLAÑOS INTL.
SAN JOSE/COSTA RICA

RWY HEADING THR

09	093°	N 09° 57' 27.73179" W 84° 08' 48.05120"
27	273°	N 09° 57' 23.67704" W 84° 07' 56.78357"

DIMENSIONS IN METERS
ELEVATIONS IN METERS
WGS 84 COORDINATES

COCO ACS (R)	119.6	COCO APP (R)	120.5	PAVAS TWR	118.3
GROUND	121.7	AP - ELEV	1002 m		




RUNWAY STRIPE: 1686 X 150

CRITICAL AREA DUE TO RELOADING AND BOMB THREATS

ON MARKED PART OF MOVING AREA :

CAUTION IS ADVISED ON AIRCRAFTS TAXIING/TOWING DUE TO LACK OF VISIBILITY OF AIR TRAFFIC SERVICES.
ON MOVING AREA, HAVING TO APPROVE TAXIING OR OTHER MOVEMENTS AT USERS DISCRETION.

SIGNALS RWY 09 / 27



LIGHTING AIDS RWY 09 / 27

